Maryland Historical Trust

Maryland Inventory of Historic Properties number: HO-652
Maryland Inventory of Historic Properties number: HO-652. Name: HO6/Altolave. ova Weep Rem
The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.
MARYLAND HISTORICAL TRUST Eligibility Recommended Eligibility Not Recommended X
Criteria:ABCD Considerations:ABCDEFGNone Comments:
Reviewer, OPS:_Anne E. Bruder Date:3 April 2001

Date:__3 April 2001

Reviewer, NR Program: Peter E. Kurtze

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/ MARYLAND HISTORICAL TRUST


MHT No. <u>HO-652</u>

SHA Bridge No. HO 61 Bridge name Athol Avenue over Deep Run
LOCATION: Street/Road name and number [facility carried] Athol Avenue
City/town Elkridge Vicinity X
County Howard
This bridge projects over: Road Railway WaterX Land
Ownership: State County X Municipal Other
HISTORIC STATUS: Is bridge located within a designated historic district? Yes No _X National Register-listed district National Register-determined-eligible district Locally-designated district Other
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete Stone Arch Bridge
Metal Truss Bridge _
Movable Bridge: Swing: Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder: Rolled Girder: Rolled Girder: Plate Girder: Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete: Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name

DESCRIPTION: Setting: Urban Small town X Rural Describe Setting: Bridge HO 61 carries Athol Avenue over Deep Run in the vicinity of Elkridge. The setting is residential, with houses on either side of the creek. The road runs in a generally east west direction.
Describe Superstructure and Substructure: Bridge HO 61 is a single span concrete slab bridge, built in 1945, with a span length of 26 feet and an overall structure length of 28 feet. There is a 21.5-foot clear roadway width between W-beam guardrails. The guardrails have replaced the parapets. The concrete slab is supported by stone masonry abutments. The bridge was rehabilitated in 1983. The overall condition of the superstructure is good. There is an irregular, transverse, 1/4" wide crack in the pavement behind both abutments.
The overall condition of the substructure is satisfactory. The top of the west abutment sounds hollow from the centerline to the north facia. The northwest wingwall exhibits loss of stone and mortar. The remaining walls exhibit minor loss.
Discuss Major Alterations: Modern guardrails have replaced the parapets. The 1995 County inspection reports states that the superstructure was replaced in 1983.
HISTORY:
WHEN was bridge built 1945 This date is: Actual X
WHY was bridge built? The need for a more efficient transportation network and increased load capacity.
WHO was the designer? Unknown
WHO was the builder? Unknown
WHY was bridge altered? Unknown
Was bridge built as part of organized bridge-building campaign? Unknown

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have National Register significance for its association with: A - Events B- Person
C- Engineering/architectural character
This bridge does not have National Register significance.
Was the bridge constructed in response to significant events in Maryland or local history? The bridge was not constructed in response to significant events in Maryland of local history.
When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area? There is no evidence that the construction of this bridge significantly affected the development and growth of the area.
Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic/visual character of the potential district? No, this bridge is not located in an area which is eligible for historic designation
Is the bridge a significant example of its type? No, this bridge is not a significant example of a concrete slab.
Does bridge retain integrity of important elements described in Context Addendum? This bridge does not retain integrity of its character defining elements because the parapets have been replaced with guardrails. Furthermore, inspection reports state that the entire superstructure was replaced in 1983.
Is bridge a significant example of work of manufacturer, designer and/or engineer? Manufacturer, designer and/or engineer of this bridge is unknown.
Should bridge be given further study before significance analysis is made? No further evaluation is necessary to determination National Register significance.
BIBLIOGRAPHY:
County inspection/bridge files X SHA inspection/bridge files Other (list):
SURVEYOR/SURVEY INFORMATION:
Date bridge recorded 8/95
Name of surveyor <u>Leo Hirrell</u> Organization/Address <u>P.A.C. Spero & Company, 40 W. Chesapeake Ave., Suite 412, Baltimore, Maryland, 21204</u>
Phone number (410) 296-1635 FAX number (410) 296-1670





40-652 HOG ATOLL AVENUE OVER DEED KUN HOWARD CO., MD PHALL 8/98 MD SHPO NOWTH APPROACH 10F8



HO-657 HOLL ATOLL AVENUE OUER DEEP A'CN HOWARD CO., MD 8/98 MD SHPO SOUTH APPROACH 20F 8



-10-652 HOLL ATOLL AVENUE OVER DEEPRON HOWARD CO., MD C. HALL 8/98 MD SHPO WEST ELEVATION. NE VIEW 3 OF 8



HO-652 HOGI ATOLL AVENUE OVER DEEP RUN HOWARD CO, MD Q. FLALL 8/98 MD SHPO EAST ELEVATION, SW VIEW 4068



40-652 HOGI ATOLL FIENUE OVER DEEP RON HOWARD Co., MD C. HALL 8/98 MD 5HPO WEST ELEVATION, SE VIEW 5 of 8



40-652 HOGI FROLL AVENUE OVER DEEP RUN HOWARD CO., MD C. HALL 8/98 MD SHPO EAST RAILING Le 07 8



HO-652
HOLL ATOLL AVENUE OVER DEEP RUN
HOWARD Co., MD
C. HALL
8/98
MD SHPO
7 OF 8



40-652 4061 FTOLL AVENUE OVER DEEP RUN HOWARD (C., MD C. HALL 8/98 MD SHPO EAST ELEVATION, SW VIEW 8 of 8